

25X1A

[]-2275-63

Copy 7 of 7

27 February 1963

MEMORANDUM FOR : The Record

SUBJECT : OXCART Status Summary - 26 February 1963

1. Aircraft #123 (J-75 engines) made flight #46 on 26 February for one hour and fifty-three minutes. Purpose of flight was to test inertial navigation system (INS) and Eastman camera. Because of an aircraft right-hand generator malfunction which disrupted electrical power to the INS, this system could not be tested. Preliminary reports indicate that the camera worked satisfactorily throughout the flight.

2. Aircraft #124 (J-75 engines) made flight #32 on 26 February for one hour and twenty-two minutes. Purpose of flight was inflight refueling pilot training. Approximately twelve dry (no fuel transferred) hook-ups were made successfully with the refueling aircraft. No problems were reported.

3. Installation of foreign object damage (FOD) circumferential inlet screens is almost complete on aircraft #122. Both JT11D-20 (J-58) engines have been reinstalled with ground runs scheduled 27 or 28 February.

4. FOD circumferential inlet screen installation continues on aircraft #121 and #125. Both JT11D-20 engines have been reinstalled in both aircraft.

25X1A /S/

[]
Development Division
OSA/DD/R

25X1A

[]:DD/OSA:haj (27 Feb 63)

Dist:

Copies 1 & 2 - DD/R
3 - AD/OSA
4 - C/DD/OSA
5 - DD/OSA
6 - C/DD/OSA (Chrono)
7 - RB/OSA

25X1A

Handle via []